



ACCESSORIES

Front Mounting Plates

Fix by drill and bolt or weld on assembly

ORDER CODE	A	B	C	D	H dia	TO SUIT MODELS
MP1	79	60	64	44	10.5	MG1
MP2	57	40	38	20	6.5	MG2
MP3	41	25	35	19	6.5	MG3
MP4	71	50	58	38	8.3	MG4
MP5	64	45	48	32	8.3	MG5
MP6	82	60	77	57	10.5	MG6
MP7	40	27	26	12.5	6.5	MG7
MP8	41	25	38	26	5.5	MH4
MP9	45	29	42	26	6.5	MH6
MP10	60	43	59	41	8.5	MH8
MP11	70	42	60	42	8.5	MH12




Bolt Adjustment Spindle

ORDER CODE	A	B
M640	6	40
M650	6	50
M845	8	45
M876	8	76
M1060	10	60
M1076	10	76
M1276	12	76
M12100	12	100


Swivel Foot Adjustment Spindle

ORDER CODE	A	B	C	D
SM665	6	50	12.5	12
SM865	8	65	17.5	18
SM885	8	85	17.5	18
SM1075	10	75	19	20
SM1265	12	65	19	20
SM1285	12	85	19	20



Neoprene Tipped Adjustment Spindle

ORDER CODE	A	B	C	D	E
NM645	6	45	15	12	12
NM670	6	70	15	12	12
NM875	8	75	20	16	16
NM895	8	95	20	16	16
NM1080	10	80	28	22	22
NM10100	10	100	28	22	22
NM1280	12	80	30	24	24
NM12100	12	100	30	24	24



Neoprene Caps

ORDER CODE	A	B	C	D
NP6	6	10	15	12
NP8	8	13	19	16
NP10	10	14	24	20

